

CA2125 Gas Micro Battery Pack
Description of issue:

It has come to our attention that with the older Gas Micro battery packs manufactured prior to January 2006, there is the possibility that the insulating material may wear through in places, creating a potential for the battery pack to short out against the Gas Micro enclosure.

The suppliers manufacturing processes changed for these battery packs in 2006, which resulted in a thicker insulating material being utilized, eliminating the potential for wear through.

Resolution:

Supply all affected end users with insulating plates, to be attached to the battery pack as detailed in images below.

It is suggested that these insulating plates are installed on the next scheduled maintenance visit on the Gas Micro units.

